



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

0001

Inspection Report

Minerals Regulatory Program

Date: June 1, 2009

Reviewed: LR

Mine Name: Grantsville Quarry	Permit Number: M0450028
Operator Name: Chemical Lime	Inspection Date: 05/26/2009
Inspector(s): Leslie Heppler	Time: 2:30 pm
Other Participants: Brett Gregory & Vicky Dyson	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Amount: \$398,300 **Bond renewal Date** 09/23/2007 **Permit fee:** \$500 due - invoice sent out 06/20/2009

Purpose of Inspection: Routine Annual Inspection, last inspection date 03/15/2007

Inspection Summary: Mine status is listed as active. There is a \$398,300 surety bond with Travelers. At the time of inspection, the process plant was not operating, but the operation was currently cleaning up the parts lay down yard. There were no haul trucks on site at the mine, and just one blast hole rig. Erosion control was functioning well along the main haul road. One of the older smaller pits had an overturned highwall, but the area was bermed off. Attached photos document the site.

Conclusions and Recommendations: The bond renewal date is past due for escalation. The operator should reclaim the area or should update the Notice of Intention and a bond escalation should be done to match current pricing for reclamation. A bond escalation letter was sent to the operator on 05/08/2009. Reclaiming part of the area would decrease the escalation amount.

Inspector's Signature Leslie Heppler

LAH:vs

cc: Brett Wilson

BLM - larry_garahana@blm.gov Stephen_Allen@blm.gov SITLA - Jblake@utah.gov

O:\M045-Tooele\M0450028-ChemicalLime\inspections\insp-05262009.doc

0001



Process Plant



Overhanging highwall - pit bermed off



Mine pit - note drill on ridge



Erosion control on haul road



Lay down yard



Lay down yard



Lay down yard



Lay down yard